

Total Land Subsidence in the Willcox and Kansas Settlement Areas, Cochise County  
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data

© MDA 2010 - 2017

Time Period of Analysis: 7.0 Years 05/05/2010 To 04/22/2017

### Explanation

05/05/2010 To 04/22/2017

#### Total Land Subsidence

Decorrelation/No Data
Greater 40 cm (15.7 in)
25 - 40 cm (9.8 - 15.7 in)
15 - 25 cm (5.9 - 9.8 in)
10 - 15 cm (3.9 - 5.9 in)
6 - 10 cm (2.4 - 3.9 in)
4 - 6 cm (1.6 - 2.4 in)
2 - 4 cm (0.8 - 1.6 in)
1 - 2 cm (0.4 - 0.8 in)
0 - 1 cm (0 - 0.4 in)

Subsidence Feature

Hardrock

Earth Fissures

#### Highways and Interstates


Interstate

US

State

Roads

Railway



1:250,000

0 1.5 3 6 9 12 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey. For information on earth fissures visit: [www.azgs.gov/EFC](http://www.azgs.gov/EFC)

Coordinate System: NAD 1983 UTM Zone 12N  
Projection: Transverse Mercator  
Datum: North American 1983  
Units: Meter  
Created: 10/11/2017

